



BULLETIN

Date	Bulletin
1/4/2012	112

Item	Description	Qty	Rate	Total
TK HK0413	HOSE CLAMP 3/16 IN BOLT HOLE 1/4 IN	0	0.91	0.00T
TK HK0709	HOSE CLAMP 3/8 IN BOLT HOLE 9/32 IN	0	1.20	0.00T
TK HK1013	HOSE CLAMP 9/16 IN BOLT HOLE 13/32 IN	0	0.39	0.00T
TK HK1113	HOSE CLAMP 5/8 IN BOLT HOLE 13/32 IN	0	0.33	0.00T
TK HK1313	HOSE CLAMP 3/4 IN BOLT HOLE 13/32 IN	0	0.45	0.00T
TK HK1513	HOSE CLAMP 7/8 IN BOLT HOLE 13/32 IN	0	0.43	0.00T
TK HK1613	HOSE CLAMP 15/16 IN BOLT HOLE 13/32 IN	0	0.63	0.00T
TK HK1813	HOSE CLAMP 1-1/16 IN BOLT HOLE 13/32 IN	0	0.88	0.00T
TK HK2117	HOSE CLAMP 1-1/4 IN BOLT HOLE 17/32 IN	0	0.86	0.00T
TK HK2317	HOSE CLAMP 1-3/8 IN BOLT HOLE 17/32 IN	0	1.19	0.00T
TK HK2517	HOSE CLAMP 1-1/2 IN BOLT HOLE 17/32 IN	0	1.23	0.00T
TK HK2617	HOSE CLAMP 1-9/16 IN BOLT HOLE 17/32 IN	0	1.41	0.00T
TK HK2917	HOSE CLAMP 1-3/4 IN BOLT HOLE 17/32 IN	0	1.49	0.00T
TK HK3117	HOSE CLAMP 1-7/8 IN BOLT HOLE 17/32 IN	0	1.56	0.00T
TK HK3217	HOSE CLAMP 1-15/16 IN BOLT HOLE 17/32 IN	0	1.61	0.00T
TK HK3317	HOSE CLAMP 2 IN BOLT HOLE 17/32 IN	0	1.79	0.00T
TK HK3417	HOSE CLAMP 2-5/32 IN BOLT HOLE 17/32 IN	0	3.25	0.00T
	Sales Tax OCT 2011 TO PRESENT		8.75%	0.00

IMPORTANT: Bulletins are date sensitive, these may be superseded by quotes, new bulletins, etc. Items may be discontinued for new models or without notice. See terms & conditions at our website. HOSE LINE 6060 San Fernando Rd Glendale CA 91202 USA www.HoseLine.Net Phone +1 818 547 3010 Fax +1 818 547 3339 Sales@HoseLine.Net